



Q-DAS[®] qs-Stat[®] K fields



K field	Available by default	Corresponding field in Gage Explorer
K0006	<input checked="" type="checkbox"/>	
K0007	<input checked="" type="checkbox"/>	
K0008	<input checked="" type="checkbox"/>	
K0009	<input checked="" type="checkbox"/>	
K0010	<input checked="" type="checkbox"/>	
K0011	<input checked="" type="checkbox"/>	
K0012	<input checked="" type="checkbox"/>	
K0013	<input checked="" type="checkbox"/>	
K0053	<input checked="" type="checkbox"/>	
K1001	<input checked="" type="checkbox"/>	Part Program - General Parameters - Name
K1002	<input checked="" type="checkbox"/>	Part Program - General Parameters - Long Description
K1003	<input checked="" type="checkbox"/>	Part Program - General Parameters - Short Description
K1005	<input checked="" type="checkbox"/>	
K1007	<input checked="" type="checkbox"/>	Part Program - General Parameters - Code
K1010	<input checked="" type="checkbox"/>	
K1040	<input checked="" type="checkbox"/>	
K1042	<input checked="" type="checkbox"/>	Part Program - General Parameters - Drawing edition
K1043	<input checked="" type="checkbox"/>	Part Program - General Parameters - Drawing number
K1044	<input checked="" type="checkbox"/>	
K1061	<input checked="" type="checkbox"/>	Global Parameters - General - Customer
K1310	<input checked="" type="checkbox"/>	
K1320	<input checked="" type="checkbox"/>	
K1900	<input checked="" type="checkbox"/>	
K2001	<input checked="" type="checkbox"/>	Measure - General Parameters - M#
K2002	<input checked="" type="checkbox"/>	Measure - General Parameters - Long Description
K2003	<input checked="" type="checkbox"/>	Measure - General Parameters - Short Description
K2004	<input checked="" type="checkbox"/>	Measure - General Parameters - Attribute
K2005	<input checked="" type="checkbox"/>	
K2006	<input checked="" type="checkbox"/>	
K2007	<input checked="" type="checkbox"/>	
K2011	<input checked="" type="checkbox"/>	
K2013	<input checked="" type="checkbox"/>	
K2022	<input checked="" type="checkbox"/>	Measure - General Parameters - Abs. Decimals
K2025	<input checked="" type="checkbox"/>	
K2030	<input checked="" type="checkbox"/>	
K2031	<input checked="" type="checkbox"/>	
K2060	<input checked="" type="checkbox"/>	
K2071	<input checked="" type="checkbox"/>	Measure - General Parameters - Nominal Value
K2072	<input checked="" type="checkbox"/>	Conversion factor: Relative --> Absolute
K2080	<input checked="" type="checkbox"/>	Fixed = 0
K2100	<input checked="" type="checkbox"/>	
K2101	<input checked="" type="checkbox"/>	Measure - General Parameters - Nominal Value



K2110	<input checked="" type="checkbox"/>	LSL (calculated)
K2111	<input checked="" type="checkbox"/>	USL (calculated)
K2112	<input checked="" type="checkbox"/>	Measure - General Parameters - LSL
K2113	<input checked="" type="checkbox"/>	Measure - General Parameters - USL
K2120	<input checked="" type="checkbox"/>	Lower Limit Type
K2121	<input checked="" type="checkbox"/>	Upper Limit Type
K2130	<input checked="" type="checkbox"/>	
K2131	<input checked="" type="checkbox"/>	
K2141	<input checked="" type="checkbox"/>	
K2142	<input checked="" type="checkbox"/>	Measure - General Parameters - Abs. UoM
K2143	<input checked="" type="checkbox"/>	Measure - General Parameters - UoM
K2144	<input checked="" type="checkbox"/>	Measure - General Parameters - Nominal Value
K2145	<input checked="" type="checkbox"/>	Conversion factor: Relative --> Absolute
K2201	<input checked="" type="checkbox"/>	
K2202	<input checked="" type="checkbox"/>	Online (Gauge Capability)
K2205	<input checked="" type="checkbox"/>	Online (Gauge Capability)
K2211	<input checked="" type="checkbox"/>	
K2212	<input checked="" type="checkbox"/>	
K2213	<input checked="" type="checkbox"/>	
K2215	<input checked="" type="checkbox"/>	
K2220	<input checked="" type="checkbox"/>	Online (Gauge Capability)
K2221	<input checked="" type="checkbox"/>	Online (Gauge Capability)
K2244	<input checked="" type="checkbox"/>	Fixed = -1
K2245	<input checked="" type="checkbox"/>	Fixed = -1
K2301	<input checked="" type="checkbox"/>	
K2302	<input checked="" type="checkbox"/>	Machines - General Parameters - Short Description
K2303	<input checked="" type="checkbox"/>	Global Parameters - General - Department
K2305	<input checked="" type="checkbox"/>	Machines - General Parameters - ID#
K2306	<input checked="" type="checkbox"/>	Global Parameters - General - Plant
K2307	<input checked="" type="checkbox"/>	
K2311	<input checked="" type="checkbox"/>	Measure - General Parameters - Work Operation
K2312	<input checked="" type="checkbox"/>	
K2313	<input checked="" type="checkbox"/>	
K2342	<input checked="" type="checkbox"/>	
K2343	<input checked="" type="checkbox"/>	
K2344	<input checked="" type="checkbox"/>	
K2401	<input checked="" type="checkbox"/>	Gages - Gage Parameters - Short Description
K2402	<input checked="" type="checkbox"/>	Gages - Gage Parameters - ID#
K2404	<input checked="" type="checkbox"/>	
K2405	<input checked="" type="checkbox"/>	
K2406	<input checked="" type="checkbox"/>	
K2407	<input checked="" type="checkbox"/>	
K2408	<input checked="" type="checkbox"/>	
K2409	<input checked="" type="checkbox"/>	
K2410	<input checked="" type="checkbox"/>	
K2422	<input checked="" type="checkbox"/>	
K2423	<input checked="" type="checkbox"/>	
K2900	<input checked="" type="checkbox"/>	



K8010	<input checked="" type="checkbox"/>	
K8011	<input checked="" type="checkbox"/>	
K8012	<input checked="" type="checkbox"/>	
K8013	<input checked="" type="checkbox"/>	
K8110	<input checked="" type="checkbox"/>	
K8111	<input checked="" type="checkbox"/>	
K8112	<input checked="" type="checkbox"/>	
K8113	<input checked="" type="checkbox"/>	
K8500	<input checked="" type="checkbox"/>	
K8501	<input checked="" type="checkbox"/>	
K8502	<input checked="" type="checkbox"/>	
K8504	<input checked="" type="checkbox"/>	
K8520	<input checked="" type="checkbox"/>	
K8521	<input checked="" type="checkbox"/>	
K8522	<input checked="" type="checkbox"/>	
K8523	<input checked="" type="checkbox"/>	
K8600	<input checked="" type="checkbox"/>	
K8610	<input checked="" type="checkbox"/>	
K8611	<input checked="" type="checkbox"/>	
K8612	<input checked="" type="checkbox"/>	
K8613	<input checked="" type="checkbox"/>	